

ERRATA

A COMPLIANT WALL, SUPERSONIC WIND TUNNEL E. H. Dowell

The author wishes to make the following corrections to his technical note published in the October 1978 issue of the *Aeronautical Journal*, pages 448-451:

In equation (6) a factor of 2 should be placed in front of the first summation.

In equation (13) A_N is twice the value shown.

In the section entitled 'Conditions for Zero Wall Interference', all inequality signs should be reversed.

Figure 3 should be replaced by the figure shown below.

In the section entitled 'Aeroelastic Coefficients for Zero Wall Interference', the number .5 should be replaced by 1.0.




Figure 3. Aeroelastic coefficients required for zero wall interference; divergence aeroelastic coefficient shown for reference.